
How to recycle **Ultrasint® TPU?**







1. CONTACTUS

Email us at sustainability@basf-**3dps.com** with your company name, contact person, interest in recycling TPU powder and/or parts, and the quantity available.



2. PREPARE THE PACKAGE

Ensure to pack TPU powder and TPU parts. Label each package using the labels we provided via email. These labels are essential for handling during shipment.



3. SHIP IT

Plan to send your recyclable material back to us coinciding with your next material delivery. This process ensures efficient restocking of materials and maintaining a sustainable cycle.



4. RECYCLE

BASF Forward AM recycles TPU by-products and waste, effectively converting them back into usable pellets. This sustainable approach ensures the efficient reuse of materials.



- TPU Powder: Includes cake powder and agglomerates - TPU Printed Parts



X NOT RECYCLABLE PARTS:

- Dyed, coated, or vapor smoothed
- Assembled or glued to different materials



REQUIREMENTS FOR RECYCLING:

- All powder and parts must be clean and dry.
- Avoid cross-contamination with other materials (e.g., blast media from depowdering or assembled parts).
- Minimum quantity: 200kg for powder and 50kg for parts.

QUALITY ASSURANCE: BASF Forward AM can conduct incoming goods inspection. In case of non-conformity, we will dispose of the material, with the cost borne by the supplier.